

General Environmental Incident Summary

Incident: 3823 **Date/Time Notice:** 7/14/2015 1646 **DEM Incident No:**
Responsible Party: BNSF
Date Incident: 7/14/2015 **Time Incident:** 0915 **Duration:** 5 minutes
County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 2 **Qtr:**
Lat: 46.87695 **Long:** -96.82188 **Method:** Navigation quality GPS
Location Description: BNSF Mainline #2 from 46.878561 -96.849581 to 46.8769441 -96.821876
Spill along south rail on ties and ballast 12"-18" wide
Submitted By: Ron Bergh **Affiliation:** Wenck Response Services
Address: 301 1st St NE
Suite 202
City: Mandan **State:** ND **Zip:** 58554

Received By:

Contact Person: Sandra Moore
4200 Deen Rd
Fort Worth , TX 76106

Distance Nearest Occupied Building: 100 Feet **Release Contained:** Yes
Type of Incident: Leak from locomotive fuel tank
Description of Released Contaminant: Diesel fuel
Volume Spilled: 20.00 gallons **Ag Related:** No
EPA Extremely Hazardous Substance: No **Reported to NRC:** No
Cause of Incident:
Tank over filled and fuel expanded

Risk Evaluation:

NONE

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

None. No waterways were impacted.

Action Taken or Planned:

Spilling product was contained. product on rail line was treated with Microblaze at a 6% mixture with tap water. solution was applied with a backpack style sprayer. Approximately 30 gallons of solution was applied to ground spill.

Wastes Disposal Location: recoverd product was taken to the Dilworth MN BNSF Yard for disposal by BNSF.

Agencies Involved:

Updates

Date: 7/15/2015 ***Status:*** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

According to the report, release was contained. Cass County Public Health has visited site. No follow-up required.